25X1₁

Approved For Release 2003/09/29 CIA RDP63-00313A000600130043-5

COR-0539 Copy 10f 7 6 July 1959

سرا

CHAILS BOTTOM .	Trip Report -
DUBREAL	1110 mayory -
1. Control Co	turing the period 22 - 26 June the undersigned visited the Pale Alienter to observe during launch of Discoverer IV.
2. T	Personnel contacted:
Γ	Lt. Col. Esthis
	Pajor Webb
(IN 02050) DES field	it was recommended by the undersigned that Major V. H. Webb of the office at Palo Alto be designated as the Officer to inspect and a pay loads. Although Major Webb has been associated with recommend
for a nucl operation.	. The following actions and/or procedures are also recommended.
for a nucl operation.	oer of years, his position at BYD offers good security cover for to. The following actions and/or procedures are also recommended. That CORCEA pay load acceptance specifications be reviewed and standardized as much as possible.
for a numi operation.	. The following actions and/or procedures are also recommended. That CORCHA pay load acceptance specifications be reviewed and
for a numi operation.	The following actions and/or procedures are also recommended. That CORCMA pay load acceptance specifications be reviewed and standardized as much as possible. Acceptance specifications and acceptance Form ID-250 be held or

day hold period. Although the undereigned felt that hunddity would have

missile and resove the unit during the hold period.

little effect if the temperature was held at 60°F, it was decided to lower the

NRO review(s) completed.

- during pay load recovery were reviewed. Since the item (nose cone) to be displayed will vary from the unit recovered it is suggested that the importance of strict conservable of the photography, before release, again be stressed. This is particularly important in case of water recovery and release of still photography in Hessii.
- 7. Indications are that there will be numerous operational problems during and immediately after launch that could effect the success of each flight. Some of these are; selection of proper IMC settings, pay load conditions during long periods of hold, security; and, as in the case of the last shot, when should recovery be attempted, (had shot reached exhit) on the first, the second, or the third pass? Since those in the DCC Center are not immediately of the pay load or some of Headquarters requirements, some one from Headquarters should be present during each launch to resolve such problems. Early mesignment of Lt. Col. Hurphy to Pale Alto would solve this problem.

25X1

25X1

DPO-DD/P

Dietalbuta on I

Coriga - Ch/Dap

2 - NOP/DED

3 - CORTRACTS

L - SECURITY

5 - OPERATIONS

6 - DEP File

7 - NI